



**AUDI A3: 1GRS285**

Vinnumber:	<b>WAUZZZ8V6EA141817</b>	Versionname:	<b>A3 SB Attraction 105PK</b>
First Registrationdate:	<b>10/04/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>124527</b>	Power Kw:	<b>77</b>
Bodytype:	<b>Break</b>	Body color:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OVER 25500 KM</b>	Parking lot:	<b>4330</b>
Maintenance:	<b>OK</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

GPS storage	<b>SD</b>	Central consol F	
GPS storage		Luggage cover	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	<b>No Tow bar</b>
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>205/55/16/91 H LightMetal</b>				
Winter tyres:	Fr.L.	<b>Michelin: 5 mm</b>	Fr.R.	<b>Michelin: 5 mm</b>
	Re.L.	<b>Michelin: 6 mm</b>	Re.R.	<b>Michelin: 6 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	<b>1532,88</b>
-------------------	----------------

Interior, Damaged, Acceptable	<b>0,00</b>
-------------------------------	-------------



Wing R R, Scratch(es), 67 - Polish

50,00



Backrest cover R R, Stain, Cleaning

25,00



Bumper R, Broken, Le - Replace and paint

651,00



Bumper F, Scratch(es), LI - Repair and paint (complete)

259,80



Seat cover F L, Stain, Cleaning

25,00



Bodywork, Damaged, Acceptable

0,00



Seat cover R L, Stain, Cleaning

25,00



Wing F L, Dent(s) and scratch(es), LI - Repair and paint (partial)

158,00

*No pictures to display*

Seat cover F R, Stain, Cleaning

25,00



Bonnet, Dent(s), LI - Repair and paint (complete)

314,08

