


AUDI A1 SPORTBACK: 1PZK864

Vinnumber:	WAUZZZ8XXHB034513	Versionname:	1.4 TDI 66kW
First Registrationdate:	19/10/2016	Fiscalpower:	
Expertise Mileage:	71829	Power Kw:	66
Bodytype:	Hatchback	Body color	Dark Blue
Gearbox:	MAN 5 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	4508
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Luggage cover
Windows electric F	Rear parking sensors
Windows electric R	Type of Tow bar
Cruise Control	No Tow bar
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK


Degree of wear

	185/60/15/84 H LightMetal			
Summer tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			595,00
Wheel hub cap F R, Missing, E - Replace			30,00



Rear window, Scratch(es), E - Replace		320,00
		
Ignition key, Missing, E - Replace		150,00
No pictures to display		
Alloy rim R R, Scratch(es), LI - Repair and paint (complete)		95,00
		
Wing R R, Scratch(es), Acceptable		0,00
No pictures to display		
Bonnet, Stone chip(s), Acceptable		0,00
No pictures to display		
Tailgate, Dent(s), Acceptable		0,00
No pictures to display		
Bumper R, Scratch(es), Acceptable		0,00
No pictures to display		
Door F R, Scratch(es), Acceptable		0,00
No pictures to display		