



**AUDI A6 AVANT: 1KDS207**

Vinnumber:	<b>WAUZZZ4G1FN078949</b>	Versionname:	<b>2.0 TDI ULTRA 140KW S TRONIC</b>
First Registrationdate:	<b>9/04/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>160414</b>	Power Kw:	<b>140</b>
Bodytype:	<b>Break</b>	Body color:	<b>Dark Blue</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>4625</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Seats R heated	
GPS storage		Central consol F	
GPS storage	<b>HD</b>	Luggage cover	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	<b>Tow bar fixed</b>
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	<b>Headlighting Xenon</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining leather</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>225/55/17/97 W LightMetal</b>				
Summer tyres:	Fr.L.	<b>Continental: 3 mm</b>	Fr.R.	<b>Continental: 3 mm</b>
	Re.L.	<b>Semperit: 7 mm</b>	Re.R.	<b>Semperit: 7 mm</b>

**Assistance equipment**

Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
<b>Total cost ex VAT</b>			<b>1541,38</b>
<b>Ignition key, Missing, E - Replace</b>			<b>150,00</b>



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Alloy rim R L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Bumper F, Dent(s) and scratch(es), It - Spot repair	115,56
---	--------



Alloy rim F L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Door F L, Dent(s), PDR - Paintless dent repair	63,00
--	-------



Roof, Scratch(es), LI - Repair and paint (complete)	577,80
---	--------



Door R L, Bad repair, LI - Repair and paint (complete)	0,00
--	------



Door R R, Chemical polution, LI - Repair and paint (complete)	382,02
---	--------



Wing R R, Repaired, No repair	0,00
-------------------------------	------

No pictures to display

Door F R, Dent(s), PDR - Paintless dent repair	63,00
--	-------

