



AUDI A4: 1HXV678

| | | | |
|-----------------------------------|--------------------------|--------------|---------------------------|
| Vinnumber: | WAUZZZ8K3FN017102 | Versionname: | A4 BER Ultra 136PK |
| First Registrationdate: | 24/10/2014 | Fiscalpower: | |
| Expertise Mileage: | 162063 | Power Kw: | 100 |
| Bodytype: | | Body color | Brown |
| Gearbox: | MAN 6 VIT | Paint type | Metalic |
| Transmission: | Front | Rims summer | Aluminium |
| Fueltype: | Diesel | Oil level | OK |
| Maintenance | OK | Parking lot | 2214 |
| Battery functioning | Yes | | |
| Number of doors | 4 | | |
| Number of seats | 5 | | |
| Number head rests | 5 | | |
| Rims summer | Aluminium | | |
| Category | Passenger Car | | |
| Oil level | OK | | |
| Registration Certificate Car (BE) | Yes | | |

Options

| | |
|--------------------------------|------------------------------|
| Radio CD | Central consol F |
| GPS storage | CD Rear parking sensors |
| GPS storage | |
| Windows electric F | |
| Windows electric R | |
| Cruise Control | |
| Steering wheel multifunctional | |
| Type of headlighting | Headlighting Halogen |
| Type of GPS | GPS big screen color |
| Type of Lining | Lining fabrics |
| Type of climate control | Autom climate control |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|-----------------------------------|-----------------------|-------|-----------------------|
| | 205/60/16/98 MS LightMetal | | | |
| Winter tyres: | Fr.L. | Michelin: 4 mm | Fr.R. | Michelin: 4 mm |
| | Re.L. | Michelin: 5 mm | Re.R. | Michelin: 5 mm |

Assistance equipment

| | | | |
|-------------|------------|------|------------|
| Spare wheel | Yes | Jack | Yes |
|-------------|------------|------|------------|

| | |
|--------------------------------------------------|---------------|
| Total cost ex VAT | 301,68 |
| Tailgate, Rust, LI - Repair and paint (complete) | 301,68 |



Roof, Scratch(es), Acceptable

0,00



Door F R, Dent(s), Acceptable

0,00

No pictures to display