



AUDI A6: 1H9R793

Vinnumber:	WAUZZZ4G5EN179670	Versionname:	A6 AVANT 136PK
First Registrationdate:	30/10/2014	Fiscalpower:	
Expertise Mileage:	95579	Power Kw:	100
Bodytype:	Break	Body color:	Silver
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3403
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Sun Roof electric
Windows electric F	Central consol F
Windows electric R	Luggage cover
Cruise Control	Front parking sensors
Steering wheel multifunctional	Rear parking sensors
Seats F heated	
Radio multimedia	
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/60/16/102 H LightMetal			
Winter tyres:	Fr.L.	Kleber: 6 mm	Fr.R.	Kleber: 6 mm
	Re.L.	Kleber: 2 mm	Re.R.	Kleber: 2 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			626,76
Wing R L, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Tires, Out of tolerance, Acceptable			0,00
<i>No pictures to display</i>			
Wing R R, Bad repair, Acceptable			0,00



Bumper R, Scratch(es), LI - Repair and paint (complete)

254,16



Sill outer L, Scratch(es), LI - Repair and paint (complete)

372,60

