


AUDI A3: 1FVH988

Vinnumber:	WAUZZZ8V7EA084110	Versionname:	A3 SB Attraction 105PK
First Registrationdate:	6/11/2013	Fiscalpower:	
Expertise Mileage:	129536	Power Kw:	77
Bodytype:	Hatchback	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	4805
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	SD	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/16/91 M-S LightMetal				
Summer tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Uniroyal: 7 mm	Re.R.	Uniroyal: 7 mm

Assistance equipment

Spare wheel	No	Compressor	Yes
Emergency spare wheel	No	Jack	No
Repair kit	Yes	Runflat	No

Total cost ex VAT 3074,86

Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 308,20



Bonnet, Hail damage, PDR - Hail 200,00



Door R R, Scratch(es), LI - Repair and paint (complete) 318,35



Wing F L, Scratch(es), LI - Repair and paint (complete) 220,18



Roof, Hail damage, PDR - Hail 575,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00





Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Headlight R, Scratch(es), E - Replace 396,00



Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 318,35



Wing F R, Scratch(es), LI - Repair and paint (complete) 220,18



Tailgate, Dent(s), Acceptable 0,00

No pictures to display