



**BMW 1 HATCH: GZ4377**

Vinnumber:	<b>WBA1V91080V739416</b>	Versionname:	<b>1.5 116D EFFICIENTDYNAMICS EDIT. (85KW)</b>
First Registrationdate:	<b>24/10/2016</b>	Fiscalpower:	
Expertise Mileage:	<b>54491</b>	Power Kw:	<b>85</b>
Bodytype:		Body color:	<b>Blue</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1523</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>4</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	<b>HD</b> Rear parking sensors
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	<b>Headlighting LED</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Autom climate control</b>
Level control	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>205/50/17/89 V LightMetal</b>				
Winter tyres:	Fr.L.	<b>Michelin: 6 mm</b>	Fr.R.	<b>Michelin: 6 mm</b>
	Re.L.	<b>Michelin: 8 mm</b>	Re.R.	<b>Michelin: 8 mm</b>

**Assistance equipment**

Spare wheel	<b>No</b>	Compressor	<b>No</b>
Emergency spare wheel	<b>No</b>	Jack	<b>No</b>
Repair kit	<b>No</b>		

Total cost ex VAT	713,40
Door F R, Dent(s), Acceptable	0,00



Windscreen, Stone chip(s), E - Replace 487,20



Wing F L, Scratch(es), Acceptable 0,00

*No pictures to display*

Door panel R R, Scratch(es), Acceptable 0,00

*No pictures to display*

Bumper R, Scratch(es), It - Spot repair 115,56



Door trim F L, Dent(s), Smart repair 110,64

*No pictures to display*

Certificate Of Conformity, Missing, E - Replace 0,00



Compressor, Missing, E - Replace 0,00



Jack, Missing, E - Replace 0,00

*No pictures to display*

Wing R L, Scratch(es), Acceptable 0,00

*No pictures to display*