



BMW 3: 1FSI310

Vinnumber:	WBA3K91060F932336	Versionname:	3 TOURING 316d 116PK
First Registrationdate:	9/10/2013	Fiscalpower:	
Expertise Mileage:	125765	Power Kw:	85
Bodytype:	Break	Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	4306
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		
Sport seats			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/50/17/94 H LightMetal				
Winter tyres:	Fr.L.	Bridgestone: 8 mm	Fr.R.	Bridgestone: 8 mm
	Re.L.	Bridgestone: 6,5 mm	Re.R.	Bridgestone: 6,5 mm

Assistance equipment

	Runflat	Yes
--	---------	------------

Total cost ex VAT	1173,38
-------------------	----------------

Bumper F, Scratch(es), LI - Repair and paint (complete)	211,80
---	---------------



Tailgate, Not original part, Repair/replace (lump sum) 0,00



Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Wing R R, Dent(s), Acceptable 0,00

No pictures to display

Alloy rim R R, Scratch(es), Acceptable 0,00

No pictures to display

Roof, Chemical pollution, LI - Repair and paint (complete) 481,50



Bonnet, Chemical pollution, LI - Repair and paint (complete) 290,08



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper R, Bad repair, Paint 0,00

