



BMW 5 BERLINE: 1NAD896

Vinnumber:	WBA5E51090G104509	Versionname:	2.0 520D (120KW)
First Registrationdate:	4/01/2016	Fiscalpower:	
Expertise Mileage:	141901	Power Kw:	120
Bodytype:	Berline	Body color:	Dark Brown
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3427
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
GPS storage		Luggage cover
GPS storage	HD	Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Type of headlighting	Headlighting Xenon	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/55/17/97 Y LightMetal				
Summer tyres:	Fr.L.	Uniroyal: 5 mm	Fr.R.	Uniroyal: 5 mm
	Re.L.	Uniroyal: 5 mm	Re.R.	Uniroyal: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------


Total cost ex VAT	932,32
-------------------	---------------

Wing F R, Scratch(es), Acceptable	0,00
-----------------------------------	-------------



Bumper R, Scratch(es), LI - Repair and paint (complete)

254,16



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Door F L, Scratch(es), Acceptable

0,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Bumper F R, Scratch(es), It - Spot repair

115,56



Windscreen, Stone chip(s), Acceptable

0,00



Rearview mirror basis L, Scratch(es), Acceptable

0,00



Tailgate, Scratch(es), Acceptable

0,00



Alloy rim R L, Scratch(es), Acceptable

0,00



Door R R, Scratch(es), Acceptable

0,00



Sill outer R, Scratch(es), LI - Repair and paint (complete)

372,60



Alloy rim F L, Scratch(es), Acceptable

0,00



Bonnet, Stone chip(s), Acceptable

0,00

