



BMW 2 COUPE: 1NBL166

Vinnumber:	WBA2G510X0V330096	Versionname:	2.0 218D (100 KW)
First Registrationdate:	12/01/2016	Fiscalpower:	
Expertise Mileage:	52752	Power Kw:	100
Bodytype:	Coupé	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3310
Number of doors:	2		
Number of seats:	4		
Number head rests:	4		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Steering wheel multifunctional	Front parking sensors
Seats F heated	Type of Tow bar
Radio multimedia	Tow bar removable
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining artificial leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear



205/50/17/93 V LightMetal				
Winter tyres:	Fr.L.	Bridgestone: 7 mm	Fr.R.	Bridgestone: 7 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 5 mm

Assistance equipment

Total cost ex VAT	452,60
Roof, Dent(s), PDR - Paintless dent repair	63,00



Wing R L 3P, Scratch(es), Acceptable	0,00
--------------------------------------	------

Bumper R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper F, Scratch(es), LI - Repair and paint (complete)	211,80
	
Wing R R 3P, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door F R, Dent(s), PDR - Paintless dent repair	82,80
	
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
