



**BMW 518: 1HJB042**

Vinnumber:	<b>WBA5J11000D336115</b>	Versionname:	<b>5 TOURING 518d 136PK</b>
First Registrationdate:	<b>30/07/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>105695</b>	Power Kw:	<b>100</b>
Bodytype:		Body color:	<b>Dark Brown</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Back</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>4123</b>
Maintenance:	<b>PLUS 5000 KM</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Seats electric F L
GPS storage		Seats electric F R
GPS storage	<b>HD</b>	Central consol F
Windows electric F		Luggage cover
Windows electric R		Front parking sensors
Cruise Control		Rear parking sensors
Steering wheel multifunctional		
Type of headlighting	<b>Headlighting Xenon</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining leather</b>	
Type of climate control	<b>Autom climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>225/55/17/97 Y LightMetal</b>				
Summer tyres:	Fr.L.	<b>Michelin: 3 mm</b>	Fr.R.	<b>Michelin: 3 mm</b>
	Re.L.	<b>Michelin: 3 mm</b>	Re.R.	<b>Michelin: 3 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT		<b>0,00</b>
Alloy rim R R, Scratch(es), Acceptable		<b>0,00</b>



Rearview mirror basis R, Scratch(es), Acceptable

0,00



Alloy rim F R, Scratch(es), Acceptable

0,00



Alloy rim R L, Scratch(es), Acceptable

0,00



Door R R, Scratch(es), Acceptable

0,00



Maintenance, Maintenance, P - Check

0,00



Alloy rim F L, Scratch(es), Acceptable

0,00



Windscreen, Repaired, P - Check

0,00



Bumper R, Scratch(es), Acceptable

0,00



Tailgate, Scratch(es), Acceptable

0,00



Bumper F, Scratch(es), Acceptable

0,00

