



BMW 3 TOURING: 1KTK180

Vinnumber:	WBA3K11040F840398	Versionname:	2.0 318D (100KW) TOURING
First Registrationdate:	30/06/2015	Fiscalpower:	
Expertise Mileage:	157739	Power Kw:	100
Bodytype:	Break	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2827
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	Tow bar fixed
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	NOT OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/60/16/92 W LightMetal				
Summer tyres:	Fr.L.	Bridgestone: 2 mm	Fr.R.	Bridgestone: 2 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Spare wheel	No	Compressor	No
Emergency spare wheel	No	Jack	No
Repair kit	No	Runflat	No

Total cost ex VAT 415,20

Wing R R, Dent(s), PDR - Paintless dent repair 63,00



Ignition key, Worn, Acceptable	0,00
<i>No pictures to display</i>	
Wing R R, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Wing R L, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Roof, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Bumper F R, Scratch(es), It - Spot repair	115,56



Tailgate, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing F R, Dent(s), PDR - Paintless dent repair	63,00



Rearview mirror basis L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door R L, Dent(s), PDR - Paintless dent repair	63,00



Alloy rim F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Rearview mirror basis R, Scratch(es), Smart repair	110,64



Bumper R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	