



BMW X3: 1GWY117

Vinnumber:	WBAWZ310600F63022	Versionname:	X3 sDrive18 136PK
First Registrationdate:	22/05/2014	Fiscalpower:	
Expertise Mileage:	130305	Power Kw:	100
Bodytype:	SUV	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metallic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3105
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	HD	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/60/17/99 H LightMetal				
Summer tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Dunlop: 2,3 mm	Re.R.	Dunlop: 2,3 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT 441,80

Door R R, Dent(s), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Bumper F, Bad repair, Acceptable

0,00



Wing F L, Dent(s), Acceptable

0,00

No pictures to display

Trunk lid covering R, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim R R, Scratch(es), Acceptable

0,00

No pictures to display

Door F R, Dent(s), Acceptable

0,00

No pictures to display

Door R L, Scratch(es), Acceptable

0,00

No pictures to display

Door F R, Dent(s), PDR - Paintless dent repair

82,80



Floor covering F L, Hole, E - Replace

264,00



Backrest cover F L, Scratch(es), Acceptable

0,00



Door F L, Dent(s), Acceptable

0,00

No pictures to display