



CITROEN C4 Picasso: 1GCV897

Vinnumber:	VF73A9HC8DJ835980	Versionname:	GR.C4 PICASSO Seduction 115PK
First Registrationdate:	3/01/2014	Fiscalpower:	
Expertise Mileage:	102579	Power Kw:	85
Bodytype:		Body color:	Brown
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3311
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage		Central consol F	
GPS storage	HD	Luggage cover	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	Tow bar removable
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/60/16/92 H Steel				
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			1991,18
Roof, Chemical polution, LI - Repair and paint (complete)			481,50



Bumper R, Crack, Le - Replace and paint	651,00
---	--------



Wheel cover F L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Wing R R, Dent(s), LI - Repair and paint (complete)	308,20
---	--------



Wheel cover R L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Door R R, Dent(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Wing F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Wheel cover F R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Wing R L, Dent(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Reflector, Crack, E - Replace	37,00
-------------------------------	-------



Tailgate, Dent(s) and scratch(es), LI - Repair and paint (complete)	301,68
---	--------

