



FORD TRANSIT: 1DLQ142

Vinnumber:	WF05XXBDF5CG35762	Versionname:	
First Registrationdate:	18/06/2012	Fiscalpower:	
Expertise Mileage:	276421	Power Kw:	74
Bodytype:	Transporter	Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	TRU11
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		

Options

Radio CD		Central consol F	
Windows electric F		Rear parking sensors	
Cruise Control		Type of Tow bar	No Tow bar
Type of headlighting	Headlighting Halogen		
Type of GPS	No GPS		
Type of Lining	Lining fabrics		
Type of climate control	No climate control		

Limited Technical Inspection

Airco functioning	NOT OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

195/70/15/104 M-S Steel				
Summer tyres:	Fr.L.	Continental: 9 mm	Fr.R.	Continental: 9 mm
	Re.L.	Continental: 7 mm	Re.R.	Continental: 7 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	1687,43
-------------------	----------------

Bonnet, Dent(s), PDR - Paintless dent repair	63,00
--	--------------



Bodywork, Not original part, Remove lettering	0,00
---	-------------

No pictures to display

Wing R.R. Dent(s) and scratch(es). I.I. - Repair and paint (complete)	231,15
---	---------------

Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 231,15



Bumper F R, Broken, E - Replace 123,00



Sidewall FL (LCV), Dent(s) and scratch(es), LI - Repair and paint (complete) 231,15



Ignition key, Missing, E - Replace 150,00



Rearview mirror housing R, Scratch(es), Acceptable 0,00

No pictures to display

Trunk door R R, Dent(s), Acceptable 0,00

No pictures to display

Rearview mirror L complete, Broken, E - Replace 138,00



Roof, Rust, LI - Repair and paint (complete) 361,13



Bumper F, Scratch(es), LI - Repair and paint (complete) 158,85



Wing R L, Rust, Acceptable 0,00

No pictures to display

Bumper corner R R, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover R R, Scratch(es), Acceptable 0,00

No pictures to display

Sliding door R, Dent(s) and scratch(es), LI - Repair and paint (partial) 231,15

