



FORD Fiesta: 1FRQ852

Vinnumber:	WF0DXXGAKDDC69683	Versionname:	FIESTA BER Titanium ECONetic S/S 95PK
First Registrationdate:	3/10/2013	Fiscalpower:	
Expertise Mileage:	73337	Power Kw:	70
Bodytype:		Body color:	Blue
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2102
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	SD	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	175/65/14/82 H LightMetal			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	115,56
-------------------	---------------

Wing R L, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Bumper F, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Door R L, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

No pictures to display

Door F R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Door R R, Dent(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Wing F L, Dent(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Roof, Scratch(es), Acceptable	0,00
-------------------------------	------

No pictures to display

Wing R R, Dent(s) and scratch(es), Acceptable	0,00
---	------

No pictures to display

Rear window, Not original part, Remove lettering	0,00
--	------



Door frame F L, Dent(s), It - Spot repair	115,56
---	--------

