



MERCEDES GLA: 1HYG405

Vinnumber:	WDC1569081J017076	Versionname:	2.1 GLA 200 CDI STYLE
First Registrationdate:	28/10/2014	Fiscalpower:	
Expertise Mileage:	58153	Power Kw:	100
Bodytype:	Hatchback	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3533
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

215/60/17/96 V LightMetal				
Summer tyres:	Fr.L.	Bridgestone: 5 mm	Fr.R.	Bridgestone: 5 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------


Total cost ex VAT 1533,82

Bumper F R, Scratch(es), It - Spot repair 115,56



Door R R, Bad repair, LI - Repair and paint (complete)

318,35




Door F L, Dent(s), PDR - Paintless dent repair

63,00



Interior, Dirty, Cleaning

25,00



Bumper cover R M, Dent(s) and scratch(es), E - Replace

198,00



Bumper R, Scratch(es), Acceptable

0,00

No pictures to display

Door F L, Scratch(es), Acceptable

0,00

No pictures to display

Door F L, Dent(s), PDR - Paintless dent repair

0,00

No pictures to display

Door R L, Scratch(es), LI - Repair and paint (complete)

318,35



Door R L, Scratch(es), LI - Repair and paint (complete)

0,00

No pictures to display

Bumper corner R R, Scratch(es), It - Spot repair

115,56



Bumper F, Stone chip(s), Acceptable 0,00

No pictures to display

Alloy Rims (all), Scratch(es), LI - Repair and paint (complete) 380,00

