



FORD Focus: 1HXH389

Vinnumber:	WF0KXXGCBKE87001	Versionname:	FOCUS BER ECONetic Trend 88g 105PK
First Registrationdate:	21/10/2014	Fiscalpower:	
Expertise Mileage:	112796	Power Kw:	77
Bodytype:	Hatchback	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2626
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Luggage cover	
GPS storage		Rear parking sensors	
GPS storage	HD	Type of Tow bar	No Tow bar
Windows electric F			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/16/91 H Steel				
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Total cost ex VAT			55,00
Bonnet, Bad repair, Paint			0,00



Bumper R, Repaired, No repair	0,00
<i>No pictures to display</i>	
Wheel cover R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door F L, Repaired, No repair	0,00
<i>No pictures to display</i>	
Wing R L, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Wing F R, Repaired, No repair	0,00
<i>No pictures to display</i>	
Wheel cover F R, Scratch(es), E - Replace	30,00



Tailgate, Repaired, No repair	0,00
<i>No pictures to display</i>	
Door F R, Repaired, No repair	0,00
<i>No pictures to display</i>	
Seat cover R L, Stain, Cleaning	25,00



Door R R, Repaired, No repair	0,00
<i>No pictures to display</i>	
Door R L, Repaired, No repair	0,00
<i>No pictures to display</i>	
Wing R R, Repaired, No repair	0,00
<i>No pictures to display</i>	