



RENAULT CLIO: 1UVX763

Vinnumber:	VF15RJL0H51813455	Versionname:	
First Registrationdate:	17/11/2014	Fiscalpower:	
Expertise Mileage:	55159	Power Kw:	66
Bodytype:		Body color:	Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3604
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage	HD	Luggage cover	
Windows electric F		Type of Tow bar	No Tow bar
Cruise Control			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK


Degree of wear

	185/65/15/88 T LightMetal			
Winter tyres:	Fr.L.	Firestone: 4 mm	Fr.R.	Firestone: 4 mm
	Re.L.	Firestone: 6 mm	Re.R.	Firestone: 5 mm

Assistance equipment

Total cost ex VAT	2176,44
Instruction book, Missing, E - Replace	0,00
<i>No pictures to display</i>	
Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete)	115,56





Door moulding Lower R L, Scratch(es), E - Replace 96,00



Dashboard, Scratch(es), Smart repair 110,64



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 246,56



Bumper F, Scratch(es), LI - Repair and paint (complete) 169,44



Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete) 115,56



GPS, Scratch(es), Repair/replace (lump sum) 0,00



Wing R R, Scratch(es), Acceptable 0,00

No pictures to display


Roof, Chemical pollution, LI - Repair and paint (complete) 385,20



Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 254,68



Bumper R, Dent(s) and scratch(es), Le - Replace and paint 535,20



Instruction book, Missing, E - Replace 45,00

No pictures to display