



MERCEDES C: 1HZY507

Vinnumber:	WDD2052041F121679	Versionname:	C BRE 220 BlueTEC 163PK
First Registrationdate:	12/11/2014	Fiscalpower:	
Expertise Mileage:	72643	Power Kw:	120
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2807
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	SD	Luggage cover	
GPS storage		Type of Tow bar	No Tow bar
Windows electric F			
Windows electric R			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/50/17/98 W LightMetal				
Summer tyres:	Fr.L.	Goodyear: 7 mm	Fr.R.	Goodyear: 7 mm
	Re.L.	Goodyear: 7 mm	Re.R.	Goodyear: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			923,52
Door R L, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)			95,00



Wing R L, Scratch(es), LI - Repair and paint (complete)

308,20



Bonnet, Scratch(es), 67 - Polish

0,00



Ceiling, Hole, Smart repair

64,32



Wing F R, Scratch(es), 67 - Polish

0,00



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Seat cover F L, Scratch(es), Smart repair

64,32



Wing F L, Scratch(es), 67 - Polish

0,00



Bumper F L, Scratch(es), Spot repair

115,56



Ceiling, Damaged, Smart repair

