


**RENAULT KANGOO: 1KAN177**

Vinnumber:	<b>VF1KW27B552796713</b>	Versionname:	<b>1.5 DCI 75E ZEN</b>
First Registrationdate:	<b>19/03/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>108245</b>	Power Kw:	<b>55</b>
Bodytype:		Body color:	<b>Black</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>2110</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F	
Windows electric F		Luggage cover	
Type of headlighting	<b>Headlighting Halogen</b>	Type of Tow bar	<b>No Tow bar</b>
Type of GPS	<b>No GPS</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Manual climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>195/65/15/95 M-S Steel</b>			
Summer tyres:	Fr.L.	<b>Dunlop: 2 mm</b>	Fr.R.	<b>Dunlop: 2 mm</b>
	Re.L.	<b>Dunlop: 5 mm</b>	Re.R.	<b>Dunlop: 5 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Compressor	<b>No</b>
Emergency spare wheel	<b>No</b>	Jack	<b>Yes</b>
Repair kit	<b>No</b>	Runflat	<b>No</b>

Total cost ex VAT	686,91
Wing R R, Bad repair, LI - Repair and paint (partial)	0,00





Windscreen, Repaired, No repair 0,00

No pictures to display

Wheel cover F R, Scratch(es), E - Replace 30,00



Wheel cover R L, Scratch(es), Acceptable 0,00

No pictures to display

Sliding door R, Dent(s) and scratch(es), LI - Repair and paint (complete) 318,35



Wing R L, Repaired, No repair 0,00

No pictures to display

Sill outer R, Dent(s) and scratch(es), It - Spot repair 163,56



Door F R, Dent(s), Acceptable 0,00

No pictures to display

Seat cover F R, Stain, Cleaning 25,00



Ignition key, Missing, E - Replace 150,00

