



MERCEDES C220: 1HHD459

| | | | |
|------------------------------------|--------------------------------|--------------|----------------------|
| Vinnumber: | WDD2050041F057437 | Versionname: | BlueTEC 163PK |
| First Registrationdate: | 22/07/2014 | Fiscalpower: | |
| Expertise Mileage: | 128990 | Power Kw: | 120 |
| Bodytype: | Berline | Body color: | Grey |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Back | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Maintenance: | OK | Parking lot: | 3701 |
| Maintenance: | A7 SERVICE OVER 3600 KM | | |
| Battery functioning: | Yes | | |
| Number of doors: | 4 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | |
|--------------------------------|------------------------------|-----------------------|
| Radio CD | | Seats electric F L |
| GPS storage | SD | Central consol F |
| GPS storage | | Front parking sensors |
| Windows electric F | | Rear parking sensors |
| Windows electric R | | |
| Cruise Control | | |
| Steering wheel multifunctional | | |
| Radio multimedia | | |
| Type of headlighting | Headlighting Halogen | |
| Type of GPS | GPS big screen color | |
| Type of Lining | Lining fabrics | |
| Type of climate control | Autom climate control | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|----------------------------------|-------|-------------------------|-------|-------------------------|
| 205/60/16/92 H LightMetal | | | | |
| Winter tyres: | Fr.L. | Vredestein: 5 mm | Fr.R. | Vredestein: 5 mm |
| | Re.L. | Vredestein: 3 mm | Re.R. | Vredestein: 3 mm |

Assistance equipment

| | | | |
|---|------------|------------|---------------|
| Repair kit | Yes | Compressor | Yes |
| Total cost ex VAT | | | 402,80 |
| Alloy rim F R, Scratch(es), LI - Repair and paint (complete) | | | 95,00 |



| | |
|-----------------------------------|------|
| Bumper R, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|



| | |
|-------------------------------|------|
| Wing R R, Dent(s), Acceptable | 0,00 |
|-------------------------------|------|



| | |
|---|--------|
| Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete) | 307,80 |
|---|--------|



| | |
|-------------------------------------|------|
| Maintenance, Maintenance, P - Check | 0,00 |
|-------------------------------------|------|

