


RENAULT Grand Espace: 1FFW092

Vinnumber:	VF1JKFJC649101947	Versionname:	GR.ESPACE Initiale 149PK
First Registrationdate:	18/06/2013	Fiscalpower:	
Expertise Mileage:	168894	Power Kw:	110
Bodytype:	MPV	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metallic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2432
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Seats electric F L	
GPS storage	SD	Seats electric F R	
Windows electric F		Central consol F	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	No Tow bar
Seats F heated			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/55/17/101 W LightMetal				
Summer tyres:	Fr.L.	Kleber: 6 mm	Fr.R.	Kleber: 6 mm
	Re.L.	Kleber: 7 mm	Re.R.	Kleber: 7 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
Total cost ex VAT			3898,52
Speaker cover F R, Broken, E - Replace			45,60



Interior, Dirty, Chemical cleaning

100,00



Windscreen, Scratch(es), E - Replace

0,00



Seat cover F L, Tear, Acceptable

0,00

No pictures to display

Bumper corner R L, Scratch(es), It - Spot repair

115,56



Ignition key, Missing, E - Replace

150,00



Rearview mirror housing R, Scratch(es), Acceptable

0,00

No pictures to display

Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)

254,16



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

369,84



Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

382,02



Alloy rim F R, Scratch(es), Acceptable

0,00

No pictures to display

110,84



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

369,84



Luggage space cover, Missing, E - Replace

288,00



Armrest R, Missing, E - Replace

149,00



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

382,02



Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete)

382,02



Alloy rim R L, Scratch(es), Acceptable

0,00

No pictures to display

Roof, Dent(s), PDR - Paintless dent repair

142,20



Door F L, Dent(s), Acceptable

0,00

No pictures to display

Bumper cover R M, Scratch(es), Acceptable

0,00

No pictures to display

Speaker cover R R, Broken, E - Replace

45,60



Wing F R, Crack, Le - Replace and paint

612,02

