



MERCEDES C: 1HXH132

Vinnumber:	WDD2052361F108452	Versionname:	C BRE 180 BlueTEC 116PK
First Registrationdate:	21/10/2014	Fiscalpower:	
Expertise Mileage:	120998	Power Kw:	85
Bodytype:	Break	Body color:	.
Gearbox:	MAN 6 VIT	Body color:	Black
Transmission:	Front	Paint type:	Metalic
Fueltype:	Diesel	Rims summer:	Aluminium
Battery functioning:	Yes	Oil level:	OK
Number of doors:	5	Parking lot:	2422
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L	
GPS storage		Seats electric F R	
GPS storage	SD	Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		
Level control			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/50/17/94 W LightMetal				
Summer tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1492,24
Wheel aperture R L, Dent(s), Acceptable	0,00



Door F R, Bad repair, LI - Repair and paint (complete)

254,68



Wing F R, Scratch(es), 67 - Polish

0,00



LED headlight R, Scratch(es), E - Replace

336,00



Bumper R, Scratch(es), LI - Repair and paint (complete)

169,44



Door F L, Dent(s), Acceptable

0,00



Bumper F, Scratch(es), LI - Repair and paint (complete)

169,44



Interior, Dirty, Cleaning

150,00



Door R R, Scratch(es), LI - Repair and paint (complete)

254,68



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)

95,00



Wing R R, Dent(s), PDR - Paintless dent repair

63,00

