



RENAULT Clio: 1HYP428

Vinnumber:	VF15R040H51874050	Versionname:	CLIO IV BER Business 75PK
First Registrationdate:	30/10/2014	Fiscalpower:	
Expertise Mileage:	103832	Power Kw:	55
Bodytype:	Hatchback	Body color:	Burgundy
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2106
Maintenance:	BINNEN 20 DAGEN		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage		Central consol F	
GPS storage	HD	Luggage cover	
Windows electric F		Rear parking sensors	
Cruise Control		Type of Tow bar	No Tow bar
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/60/15/88 H Steel			
Summer tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Pirelli: 5 mm	Re.R.	Pirelli: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	400,34
-------------------	---------------

Tailgate, Scratch(es), LI - Repair and paint (complete)	241,34
---	---------------



Door moulding Lower R L, Scratch(es), E - Replace	96,00
---	-------



Bumper F L, Scratch(es), Acceptable	0,00
-------------------------------------	------

No pictures to display

Door R L, Dent(s), PDR - Paintless dent repair	63,00
--	-------



Rearview mirror housing L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Door R R, Dent(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Wheel cover F R, Scratch(es), Acceptable	0,00
--	------

No pictures to display