


RENAULT Megane: 1FUZ813

Vinnumber:	VF1BZ140649831040	Versionname:	MEGANE BER Energy dynamique 110PK
First Registrationdate:	4/11/2013	Fiscalpower:	
Expertise Mileage:	83291	Power Kw:	81
Bodytype:	Hatchback	Body color:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Metallic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2121
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Sun Roof electric	
GPS storage	SD	Panoramic roof	
GPS storage		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	Tow bar fixed
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 H LightMetal			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 3 mm	Re.R.	Michelin: 3 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	2316,40
-------------------	---------

Ignition key, Missing, E - Replace	150,00
------------------------------------	--------



Rear spoiler, Hail damage, PDR - Hail	25,00
---------------------------------------	-------



Wing F R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Bonnet, Hail damage, PDR - Hail	150,00
---------------------------------	--------



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Bumper R, Deformed / Strained, Le - Replace and paint	651,00
---	--------



Roof pillar R, Hail damage, PDR - Hail	50,00
--	-------



Door F R, Dent(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Bumper F, Deformed / Strained, Le - Replace and paint 735,00



Bumper grille, Broken, E - Replace 32,40



Wing R R, Hail damage, PDR - Hail 25,00



Bumper moulding F M, Deformed / Strained, E - Replace 125,00



Roof pillar L, Hail damage, PDR - Hail 25,00



Interior, Dirty, Acceptable 0,00

No pictures to display

Door R R, Dent(s), PDR - Paintless dent repair 63,00

