



RENAULT MEGANE: QF8528

Vinnumber:	VF1BZ690JS3899337	Versionname:	1.5 DCI 110 EDC BOSE ? EDITION
First Registrationdate:	9/11/2015	Fiscalpower:	
Expertise Mileage:	74610	Power Kw:	81
Bodytype:	Hatchback	Body color:	Dark Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1405
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Sun Roof electric
Windows electric F	Panoramic roof
Windows electric R	Central consol F
Cruise Control	Luggage cover
Steering wheel multifunctional	Front parking sensors
Radio multimedia	Rear parking sensors
Type of headlighting	Type of Tow bar
Type of GPS	Headlighting Halogen
Type of Lining	GPS big screen color
Type of climate control	Lining semi-artificial leather
	Autom climate control
	No Tow bar

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	NOT OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/50/17/95 V LightMetal			
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	330,20
-------------------	---------------

Alloy rim F L polished, Scratch(es), Acceptable	0,00
---	-------------

No pictures to display

Alloy rim F R polished, Scratch(es), E - Replace	235,20
--	---------------



Wing R R, Repaired, Acceptable	0,00
--------------------------------	------

No pictures to display

Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete)	95,00
---	-------

