



SEAT Alhambra: 1JKK527

Vinnumber:	VSSZZZ7NZFV514015	Versionname:	ALHAMBRA E-Ecomotive Style 140PK
First Registrationdate:	9/01/2015	Fiscalpower:	
Expertise Mileage:	123920	Power Kw:	103
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3301
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L	
GPS storage		Seats electric F R	
GPS storage	HD	Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Type of Tow bar	No Tow bar
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/50/17/98 H LightMetal				
Summer tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Continental: 6 mm	Re.R.	Continental: 6 mm

Assistance equipment

Total cost ex VAT	726,82
Door moulding Lower R R, Strained , Smart repair	110,64



Bodywork, Glue residues, Remove lettering 0,00

No pictures to display

Roof, Hail damage, PDR - Hail 0,00



Tailgate, Deformed / Strained, LI - Repair and paint (complete) 362,02



Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete) 254,16



Bumper F, Scratch(es), Acceptable 0,00

No pictures to display

Alloy Rims (all), Scratch(es), Acceptable 0,00

No pictures to display