


**PEUGEOT 308: 1HXX998**

Vinnumber:	<b>VF3LBBHXHES177571</b>	Versionname:	<b>308 BER BlueHDi Allure STT 116PK</b>
First Registrationdate:	<b>29/07/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>182659</b>	Power Kw:	<b>85</b>
Bodytype:	<b>Hatchback</b>	Body color:	<b>Blue</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metallic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1331</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F
GPS storage		Luggage cover
GPS storage	<b>HD</b>	Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	<b>Headlighting LED</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining fabrics</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>205/55/16/91 H LightMetal</b>			
Summer tyres:	Fr.L.	<b>Firestone: 5 mm</b>	Fr.R.	<b>Firestone: 5 mm</b>
	Re.L.	<b>Firestone: 6 mm</b>	Re.R.	<b>Firestone: 6 mm</b>

**Assistance equipment**

Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
Total cost ex VAT			<b>864,72</b>
Rocker panel inner R L, Dent(s), Acceptable			<b>0,00</b>
<i>No pictures to display</i>			
Door F L, Dent(s), PDR - Paintless dent repair			<b>63,00</b>



Outer door handle R L, Scratch(es), Acceptable 0,00

No pictures to display

Door F R, Dent(s), PDR - Paintless dent repair 63,00



Seat cover F R, Dirty, Cleaning 25,00



Bumper F L, Scratch(es), Acceptable 0,00

No pictures to display

Bumper corner R R, Scratch(es), It - Spot repair 115,56



Wing R L, Scratch(es), It - Spot repair 115,56



Alloy Rims (all), Scratch(es), LI - Repair and paint (complete) 380,00





Rocker panel inner R R, Scratch(es), Acceptable	0,00
---	------

*No pictures to display*

Roof, Dent(s), PDR - Paintless dent repair	102,60
--	--------



Bonnet, Stone chip(s), Acceptable	0,00
-----------------------------------	------

*No pictures to display*