


NISSAN Qashqai: 1HRN629

| | | | |
|------------------------------------|--------------------------|--------------|--------------------------------------|
| Vinnumber: | SJNFAAJ11U1178260 | Versionname: | QASHQAI 2WD Business Ed.110PK |
| First Registrationdate: | 15/09/2014 | Fiscalpower: | |
| Expertise Mileage: | 144253 | Power Kw: | 81 |
| Bodytype: | | Body color: | Black |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Maintenance: | NOT OK | Parking lot: | 2523 |
| Battery functioning: | Yes | | |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | | |
|--------------------------------|------------------------------|-----------------------|-------------------|
| Radio CD | | Central consol F | |
| GPS storage | | Luggage cover | |
| GPS storage | SD | Front parking sensors | |
| Windows electric F | | Rear parking sensors | |
| Windows electric R | | Type of Tow bar | No Tow bar |
| Cruise Control | | | |
| Steering wheel multifunctional | | | |
| Radio multimedia | | | |
| Type of headlighting | Headlighting Halogen | | |
| Type of Lining | Lining fabrics | | |
| Type of climate control | Autom climate control | | |
| Adaptive cruise control | | | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|----------------------------------|-------|---------------------|-------|---------------------|
| 215/60/17/96 H LightMetal | | | | |
| Winter tyres: | Fr.L. | Dunlop: 5 mm | Fr.R. | Dunlop: 5 mm |
| | Re.L. | Dunlop: 6 mm | Re.R. | Dunlop: 6 mm |

Assistance equipment

| | | | |
|-----------------------|------------|------|------------|
| Emergency spare wheel | Yes | Jack | Yes |
|-----------------------|------------|------|------------|

Total cost ex VAT 1297,26

Trunk lid covering R, Scratch(es), Acceptable 0,00

No pictures to display

Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 318,35



| | |
|---|--------|
| Alloy rim F R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Door F L, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Bonnet, Stone chip(s), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Wing R R, Scratch(es), LI - Repair and paint (complete) | 308,20 |



| | |
|---|--------|
| Bumper R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Door R R, Scratch(es), LI - Repair and paint (complete) | 318,35 |



| | |
|--|--------|
| Alloy rim F L, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete) | 115,56 |



| | |
|---|--------|
| Bumper moulding R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Bumper F, Scratch(es), LI - Repair and paint (complete) | 211,80 |



| | |
|---|-------|
| Wing F L, Dent(s) and scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Door R L, Dent(s) and scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Bumper spoiler F, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Backrest cover R M, Stain, Cleaning | 25,00 |

