



TOYOTA AYGO: SF6904

Vinnumber:	JTDKGN50N135577	Versionname:	1.0 VVT-I X-PLAY MMT
First Registrationdate:	7/01/2016	Fiscalpower:	
Expertise Mileage:	79394	Power Kw:	51
Bodytype:		Body color:	Black
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Petrol	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2116
Number of doors:	5		
Number of seats:	4		
Number head rests:	4		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F	Luggage cover
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	NOT OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	165/60/15/77 T Steel			
Winter tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	1401,26
-------------------	---------

Bodywork, Not original part, Acceptable	0,00
---	------



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete)	169,44
---	--------



Wing F L, Dent(s), PDR - Paintless dent repair 63,00

No pictures to display

Door F R, Scratch(es), LI - Repair and paint (complete) 254,68



Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Dent(s), Acceptable 0,00

No pictures to display

Door F L, Dent(s), Acceptable 0,00

No pictures to display

Floor covering F L, Hole, E - Replace 240,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 169,44



Wheel cover F L, Scratch(es), Acceptable 0,00

No pictures to display

Door F L, Dent(s), PDR - Paintless dent repair 63,00



Ignition key, Missing, E - Replace 150,00



Wing R L, Dent(s), Acceptable 0,00

No pictures to display

Wing F R, Scratch(es), LI - Repair and paint (complete) 176,14



Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete) 115,56

