



VOLKSWAGEN Sharan: 1HFY008

Vinnumber:	WVWZZZ7NZFV002617	Versionname:	SHARAN Comfortline BMT DSG 177PK Aut.
First Registrationdate:	10/07/2014	Fiscalpower:	
Expertise Mileage:	174665	Power Kw:	130
Bodytype:		Body color:	Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3523
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
GPS storage	HD	Luggage cover
GPS storage		
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

215/60/16/95 V LightMetal				
Summer tyres:	Fr.L.	Firestone: 5 mm	Fr.R.	Firestone: 5 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment

Total cost ex VAT	0,00
Interior, Dirty, Cleaning	0,00



Wing F L, Dent(s), PDR - Paintless dent repair 0,00




Wing R R, Dent(s) and scratch(es), Le - Replace and paint 0,00



Wing F L, Scratch(es), Acceptable 0,00

No pictures to display

Rocker panel inner R L, Dent(s), PDR - Paintless dent repair 0,00



Alloy rim R R, Scratch(es), Acceptable 0,00

No pictures to display

Door F R, Dent(s) and scratch(es), Le - Replace and paint 0,00



Door F L, Scratch(es), It - Spot repair 0,00



Door R R, Dent(s) and scratch(es), Le - Replace and paint 0,00



Alloy rim R L, Scratch(es), Acceptable 0,00

No pictures to display

Sill outer R, Dent(s) and scratch(es), Le - Replace and paint 0,00



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete) 0,00





Ignition key, Missing, E - Replace

0,00

No pictures to display