



VOLKSWAGEN Caddy: 1JEE692

Vinnumber:	WV2ZZZ2KZFX055342	Versionname:	CADDY MAXI LIFE Trendl.102PK OMBOUW Dub.
First Registrationdate:	24/11/2014	Fiscalpower:	
Expertise Mileage:	169367	Power Kw:	75
Bodytype:		Body color:	Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2329
Maintenance:	10700KM		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Rear parking sensors
Cruise Control	Type of Tow bar
Type of headlighting	Headlighting Halogen
Type of Lining	Lining fabrics
Type of climate control	Manual climate control
	No Tow bar

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/94 V Steel			
Summer tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Dunlop: 5 mm	Re.R.	Dunlop: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	279,15
-------------------	--------

Bumper F, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Wing F R, Dent(s), Acceptable	0,00
-------------------------------	------



Internal Boot Lining R, Scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Dent(s), LI - Repair and paint (complete) 279,15



Wheel cover R L, Scratch(es), Acceptable 0,00

No pictures to display

Sliding door R, Scratch(es), Acceptable 0,00



Bonnet, Scratch(es), Acceptable 0,00

No pictures to display

Internal Boot Lining L, Scratch(es), Acceptable 0,00

No pictures to display


Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Door F R, Dent(s) and scratch(es), Acceptable 0,00



Wheel cover F R, Scratch(es), Acceptable 0,00



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display