



SKODA Octavia: 1HEG430

| | | | |
|-----------------------------------|--------------------------|--------------|-------------------------------------|
| Vinnumber: | TMBJG7NE9E0227627 | Versionname: | OCTAVIA COMBI Ambition 105PK |
| First Registrationdate: | 1/07/2014 | Fiscalpower: | |
| Expertise Mileage: | 108053 | Power Kw: | 77 |
| Bodytype: | | Body color: | Blue |
| Gearbox: | MAN 5 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Steel |
| Fueltype: | Diesel | Oil level: | OK |
| Maintenance | IN 12400 KM | Parking lot: | 4806 |
| Maintenance | OK | | |
| Battery functioning | Yes | | |
| Number of doors | 5 | | |
| Number of seats | 5 | | |
| Number head rests | 5 | | |
| Rims summer | Steel | | |
| Category | Passenger Car | | |
| Oil level | OK | | |
| Registration Certificate Car (BE) | Yes | | |

Options

| | | | |
|--------------------------------|------------------------------|-----------------------|-------------------|
| Radio CD | | Central consol F | |
| GPS storage | | Luggage cover | |
| GPS storage | SD | Front parking sensors | |
| Windows electric F | | Rear parking sensors | |
| Windows electric R | | Type of Tow bar | No Tow bar |
| Cruise Control | | | |
| Steering wheel multifunctional | | | |
| Type of headlighting | Headlighting Halogen | | |
| Type of GPS | GPS big screen color | | |
| Type of Lining | Lining fabrics | | |
| Type of climate control | Autom climate control | | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|-----------------------------|-------|--------------------------|-------|--------------------------|
| 205/55/16/91 V Steel | | | | |
| Summer tyres: | Fr.L. | Other: 4 mm | Fr.R. | Other: 4 mm |
| | Re.L. | Bridgestone: 6 mm | Re.R. | Bridgestone: 6 mm |

Assistance equipment

| | | | |
|------------|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
|------------|------------|------------|------------|

| | |
|---------------------------------------|---------|
| Total cost ex VAT | 2456,75 |
| Wheel cover F R, Missing, E - Replace | 30,00 |



Luggage space cover, Scratch(es), Smart repair 110,64




Wheel cover F L, Missing, E - Replace 30,00



Wing R R, Scratch(es), LI - Repair and paint (complete) 308,20



Bonnet, Bad repair, LI - Repair and paint (complete) 290,08



Ignition key, Missing, E - Replace 150,00

No pictures to display

Roof, Chemical pollution, Acceptable 0,00

No pictures to display

Wheel cover R R, Missing, E - Replace 30,00



Door R R, Scratch(es), LI - Repair and paint (complete) 318,35



Bumper R, Crack, Le - Replace and paint 651,00





Seat cover R L, Stain, Cleaning

25,00



Wing R L, Scratch(es), Acceptable

0,00

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Tailgate, Scratch(es), LI - Repair and paint (complete)

301,68

