



SKODA FABIA COMBI: 1LUE166

Vinnumber:	TMBJJ6NJ4GZ106463	Versionname:	1.4 CRTDI 66KW AMBITION
First Registrationdate:	7/12/2015	Fiscalpower:	
Expertise Mileage:	127017	Power Kw:	66
Bodytype:		Body color	Grey
Gearbox:	MAN 5 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	4105
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Windows electric F		Central consol F	
Cruise Control		Luggage cover	
Radio multimedia		Rear parking sensors	
Type of headlighting	Headlighting Halogen	Type of Tow bar	Tow bar removable
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

185/60/15/84 H Steel				
Summer tyres:	Fr.L.	Continental: 6 mm	Fr.R.	Continental: 6 mm
	Re.L.	Other: 6 mm	Re.R.	Other: 6 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT

947,48

Bumper R, Scratch(es), LI - Repair and paint (complete)

259,80





Seat cover F R, Stain, Cleaning

25,00



Door seal F L, Deformed / Strained, E - Replace

54,00



Wheel cover F R, Scratch(es), E - Replace

30,00



Seat cover F L, Stain, Cleaning

25,00



Bodywork, Damaged, Acceptable

0,00



Tailgate, Scratch(es), LI - Repair and paint (complete)

397,68



Roof, Dent(s), LI - Repair and paint (complete)

0,00



Roof pillar R, Dent(s), PDR - Paintless dent repair

63,00



Wheel cover F L, Scratch(es), E - Replace

30,00



Wing F L, Dent(s), PDR - Paintless dent repair

63,00

