



VOLKSWAGEN Polo: 1GWA261

Vinnumber:	WVWZZZ6RZEY248891	Versionname:	POLO BlueMotion Techn.DPF 90PK
First Registrationdate:	15/05/2014	Fiscalpower:	
Expertise Mileage:	157196	Power Kw:	66
Bodytype:		Body color:	Red
Gearbox:	MAN 5 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3224
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
GPS storage	HD	Luggage cover
GPS storage		Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Manual climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	185/60/15/88 H Steel			
Summer tyres:	Fr.L.	Uniroyal: 6 mm	Fr.R.	Uniroyal: 6 mm
	Re.L.	Dunlop: 5 mm	Re.R.	Dunlop: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	96,00
Wing F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper F, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Roof, Chemical polution, Acceptable	0,00
<i>No pictures to display</i>	
Seat cover F L, Burned, E - Replace	0,00



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover R R, Missing, E - Replace 24,00



Wheel cover F R, Missing, E - Replace 24,00



Wheel cover F L, Missing, E - Replace 24,00



Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover R L, Scratch(es), E - Replace 24,00

