



**TOYOTA Auris: 1HJB110**

Vinnumber:	<b>SB1MS3JE00E103112</b>	Versionname:	<b>AURIS BER HSD Hybr.Lounge CVT 99PK Aut.</b>
First Registrationdate:	<b>30/07/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>64511</b>	Power Kw:	<b>73</b>
Bodytype:		Body color	<b>GRIJS</b>
Gearbox:	<b>Automatic</b>	Body color	<b>Grey</b>
Transmission:	<b>Front</b>	Paint type	<b>Metalic</b>
Fueltype:	<b>Hybrid Petrol</b>	Rims summer	<b>Aluminium</b>
Maintenance	<b>OK</b>	Oil level	<b>OK</b>
Battery functioning	<b>Yes</b>	Parking lot	<b>3628</b>
Number of doors	<b>5</b>		
Number of seats	<b>5</b>		
Number head rests	<b>5</b>		
Rims summer	<b>Aluminium</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		
Registration Certificate Car (BE)	<b>Yes</b>		

**Options**

Radio CD		Central consol F	
GPS storage	<b>HD</b>	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	<b>No Tow bar</b>
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining semi-leather</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**


<b>225/45/17/91 W LightMetal</b>				
Summer tyres:	Fr.L.	<b>Kleber: 5 mm</b>	Fr.R.	<b>Kleber: 5 mm</b>
	Re.L.	<b>Dunlop: 6 mm</b>	Re.R.	<b>Dunlop: 6 mm</b>

**Assistance equipment**

Repair kit	<b>No</b>	Compressor	<b>Yes</b>
------------	-----------	------------	------------

Total cost ex VAT	<b>1212,42</b>
-------------------	----------------

Roof, Dent(s), PDR - Paintless dent repair	<b>122,40</b>
--	---------------



Interior, Dirty, Chemical cleaning 175,00



Interior, Smell, Ozone treatment 152,58



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Tyre repair kit, Missing, E - Replace 35,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00







Seat cover F R, Stain, Cleaning

25,00



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Dashboard, Scratch(es), Smart repair

110,64

