



VOLKSWAGEN Polo: 1LPF436

Vinnumber:	WVWZZZ6RZEY079291	Versionname:	POLO BER Comfortline DPF DSG 90PK Aut.
First Registrationdate:	9/10/2013	Fiscalpower:	
Expertise Mileage:	143927	Power Kw:	66
Bodytype:	Hatchback	Body color:	Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3615
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	HD	Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	NOT OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	185/60/15/88 H LightMetal			
Summer tyres:	Fr.L.	Michelin: 7 mm	Fr.R.	Michelin: 7 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	1488,30
Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)	246,56



Covering interior front pillar L, Burned, Smart repair 110,64



Wing F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 176,14



Ceiling, Burned, Smart repair 64,32




Seat cover F L, Bad repair, E - Replace 312,00



Bodywork, Glue residues, Remove lettering 0,00

No pictures to display

Roof, Chemical polution, LI - Repair and paint (complete) 385,20



Wheel cover F L, Scratch(es), E - Replace 24,00



Bumper F, Scratch(es), LI - Repair and paint (complete) 169,44

