



VOLVO V60: 1HZK991

Vinnumber:	VV1FW31A1F1240710	Versionname:	V60 BRE D3 Kinetic 136PK
First Registrationdate:	6/11/2014	Fiscalpower:	
Expertise Mileage:	115593	Power Kw:	100
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2208
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
GPS storage	HD	Luggage cover
GPS storage		Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

215/50/17/92 H LightMetal				
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment


Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1179,20
-------------------	----------------

Central pillar L, Dent(s), Acceptable	0,00
---------------------------------------	-------------

No pictures to display

Bonnet, Dent(s), PDR - Paintless dent repair	181,80
--	---------------



Bumper F, Bad repair, Acceptable 0,00



Alloy rim R R, Scratch(es), E - Replace 235,20



Wing R L, Scratch(es), Acceptable 0,00

No pictures to display Bumper R, Scratch(es), Acceptable 0,00

No pictures to display Wing R R, Scratch(es), LI - Repair and paint (complete) 308,20



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Rocker panel inner R L, Scratch(es), Forfeit 75,00



Door R L, Chemical polution, Acceptable 0,00



Bumper F, Scratch(es), Acceptable 0,00

No pictures to display

Rocker panel inner F R, Scratch(es), Forfeit

75,00



Alloy rim R L, Scratch(es), Acceptable

0,00

No pictures to display

Door panel F L, Hole, E - Replace

114,00

