



VOLKSWAGEN GOLF: 1GTU754

Vinnumber:	WVWZZZAUZEW381108	Versionname:	R-LINE Highline 105PK
First Registrationdate:	28/04/2014	Fiscalpower:	
Expertise Mileage:	180657	Power Kw:	77
Bodytype:		Body color:	Blue
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	NOT OK	Parking lot:	2501
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage		Central consol F
GPS storage	SD	Luggage cover
Windows electric F		Front parking sensors
Windows electric R		Rear parking sensors
Cruise Control		
Steering wheel multifunctional		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	
Sport seats		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/45/17/94 Y LightMetal				
Summer tyres:	Fr.L.	Goodyear: 3 mm	Fr.R.	Goodyear: 3 mm
	Re.L.	Goodyear: 3 mm	Re.R.	Goodyear: 3 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	132,00
Roof pillar R, Hail damage, PDR - Hail	0,00



Backrest cover F L, Worn, Acceptable 0,00



Maintenance, Maintenance, Execute 0,00



Bonnet, Hail damage, PDR - Hail 0,00



Parking sensor R, Not functioning (well), E - Replace 0,00



Wing R R, Hail damage, PDR - Hail 0,00



Door R R, Dent(s), Acceptable 0,00

No pictures to display

Rear window, Scratch(es), Acceptable 0,00

No pictures to display

Roof, Hail damage, PDR - Hail 0,00



Bumper F, Scratch(es), Acceptable 0,00

No pictures to display

Bumper grille, Broken, E - Replace 0,00



Alloy rim R L, Scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Wing F R, Hail damage, PDR - Hail 0,00



Tyre F R, Deformed / Strained, E - Replace

132,00

