


OPEL Zafira: 1HJY236

Vinnumber:	W0LPD9E31E2097455	Versionname:	ZAFIRA TOURER ecoFLEX Enjoy St/St 136PK
First Registrationdate:	6/08/2014	Fiscalpower:	
Expertise Mileage:	92716	Power Kw:	100
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metallic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2525
Maintenance:	2-5-2018		
Maintenance:	78141 KM		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
GPS storage	HD	Luggage cover
GPS storage		Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Manual climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/50/17/94 V LightMetal				
Summer tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Bridgestone: 7 mm	Re.R.	Bridgestone: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT 987,36

Wing F L, Dent(s), PDR - Paintless dent repair 63,00



Step L, Scratch(es), Acceptable

0,00



Tailgate, Scratch(es), Acceptable

0,00



Door R R, Dent(s), Acceptable

0,00



Door F L, Scratch(es), It - Spot repair

115,56



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)

259,80



Trunk lid covering R, Scratch(es), Smart repair

110,64



Alloy rim R R, Scratch(es), Acceptable

0,00

No pictures to display

Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)

259,80



Wing F R, Dent(s), Acceptable

0,00



Door F L, Repaired, P - Check

0,00



Door frame R L, Scratch(es), Acceptable

0,00



Roof pillar L, Dent(s), Acceptable

0,00



Wing R R, Dent(s), Acceptable

0,00



Rearview mirror housing L, Scratch(es), Acceptable

0,00



Door F R, Dent(s) and scratch(es), It - Spot repair

115,56



Door frame R R, Scratch(es), Acceptable

0,00



Alloy rim R R, Scratch(es), Acceptable

0,00



Roof pillar R, Dent(s), PDR - Paintless dent repair

63,00

