



VOLVO S80: 1FGU411

Vinnumber:	YV1AS31A1D1172773	Versionname:	BER D3 Kinetic S/S 136PK
First Registrationdate:	25/06/2013	Fiscalpower:	
Expertise Mileage:	155512	Power Kw:	100
Bodytype:	Berline	Body color:	Brown
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2612
Maintenance:	GEDAAN OP 138288 KM		
Battery functioning:	Yes		
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	No		

Options

Radio CD		Central consol F	
GPS storage		Front parking sensors	
GPS storage	HD	Rear parking sensors	
Windows electric F		Type of Tow bar	Tow bar removable
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection


Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/55/16/99 W LightMetal				
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			629,58
Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete)			382,02



Bumper R, Scratch(es), Acceptable 0,00



Door panel R L, Tear, E - Replace 132,00



Wing R R, Dent(s), Acceptable 0,00



Wing R L, Scratch(es), Acceptable 0,00



Bumper F, Scratch(es), It - Spot repair 115,56

