



AUDI A3: 1DLF045

Vinnumber:	WAUZZZ8PXCA136327	Versionname:	A3 SB TDie Attract.Start/Stop DPF 105PK
First Registrationdate:	14/06/2012	Fiscalpower:	
Expertise Mileage:	90415	Power Kw:	77
Bodytype:		Body color:	Black
Gearbox:	MAN 5 VIT	Paint type:	Metallic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3207
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Windows electric F	Central consol F
Windows electric R	Luggage cover
Cruise Control	Front parking sensors
Steering wheel multifunctional	Rear parking sensors
Seats F heated	
Type of headlighting	Headlighting Halogen
Type of GPS	No GPS
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/91 H LightMetal			
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	442,92
--------------------------	---------------

Rearview mirror housing R, Scratch(es), Acceptable	0,00
---	-------------

No pictures to display

Tailgate, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Alloy Rims (all), Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Door F R, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Door R L, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Wing R L, Scratch(es), It - Spot repair

115,56



Wing R R, Rust, It - Spot repair

115,56



Bumper F, Scratch(es), Acceptable

0,00

No pictures to display

Door F L, Scratch(es), Acceptable

0,00

No pictures to display