



BMW 3: 1FOJ058

Vinnumber:	WBA3D91040J412532	Versionname:	3 BER 316d 116PK
First Registrationdate:	5/09/2013	Fiscalpower:	
Expertise Mileage:	86788	Power Kw:	85
Bodytype:	Berline	Body color:	Silver
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	-2900KM	Parking lot:	3705
Maintenance:	NOT OK		
Battery functioning:	Yes		
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	HD	Rear parking sensors	
GPS storage		Type of Tow bar	No Tow bar
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining artificial leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK


Degree of wear

205/60/16/92 W LightMetal				
Summer tyres:	Fr.L.	Goodyear: 2 mm	Fr.R.	Goodyear: 2 mm
	Re.L.	Goodyear: 1,4 mm	Re.R.	Goodyear: 1,4 mm

Assistance equipment

	Runflat	Yes
--	---------	------------

Total cost ex VAT	1525,11
Bonnet, Chemical polution, LI - Repair and paint (complete)	290,08



Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Bumper F L, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Seat cover F L, Worn, Acceptable 0,00



Tyre R R, Tear, Acceptable 0,00



Tailgate, Scratch(es), LI - Repair and paint (complete) 301,68



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 308,20



Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 318,35



Tyre R L, Flat, Acceptable 0,00



Rearview mirror housing R, Scratch(es), Acceptable 0,00

No pictures to display

Maintenance, Maintenance, Execute

0,00

No pictures to display