



AUDI A1 SPORTBACK: 1PYB697

Vinnumber:	WAUZZZ8X0HB030955	Versionname:	1.4 TDI 66kW
First Registrationdate:	11/10/2016	Fiscalpower:	
Expertise Mileage:	36170	Power Kw:	66
Bodytype:		Body color:	Blue
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3121
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage		Luggage cover	
GPS storage	SD	Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	185/60/15/84 H LightMetal			
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 7 mm	Re.R.	Michelin: 7 mm

Assistance equipment

Repair kit	Yes	Compressor Jack	Yes
------------	------------	-----------------	------------

Total cost ex VAT	1208,82
Door R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bonnet, Dent(s) and scratch(es), LI - Repair and paint (complete)	232,06



Bumper F R, Scratch(es), It - Spot repair

115,56



Alloy rim F L, Scratch(es), Acceptable

0,00

No pictures to display

Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)

169,44



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Roof pillar L, Scratch(es), Acceptable

0,00

No pictures to display

Roof, Dent(s) and scratch(es), LI - Repair and paint (complete)

385,20



Sill outer L, Dent(s) and scratch(es), It - Spot repair

211,56

