



AUDI A1: DR1310

Vinnumber:	WAUZZZ8X8EB154760	Versionname:	A1 SB Ambition S-tr.90PK Aut.
First Registrationdate:	13/10/2014	Fiscalpower:	
Expertise Mileage:	44429	Power Kw:	66
Bodytype:	Hatchback	Body color:	Black
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4615
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Seats F heated	
Radio multimedia	
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

215/45/16/90 V LightMetal				
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT 1560,76

Bonnet, Chemical polution, LI - Repair and paint (complete) 232,06



Wing R L, Scratch(es), LI - Repair and paint (complete)

246,56



Bumper R, Scratch(es), LI - Repair and paint (complete)

169,44



Door F L, Scratch(es), Acceptable

0,00

No pictures to display

Door R L, Scratch(es), LI - Repair and paint (complete)

254,68



Aerial, Damaged, E - Replace

12,00



Door F R, Scratch(es), Acceptable

0,00

No pictures to display

Certificate Of Conformity, Missing, E - Replace

150,00

No pictures to display

Tailgate, Scratch(es), LI - Repair and paint (complete)

241,34



Door R R, Scratch(es), LI - Repair and paint (complete)

254,68



Wing R R, Dent(s) and scratch(es), Acceptable

0,00

No pictures to display

Wing F R, Scratch(es), Acceptable

0,00

No pictures to display