



AUDI A3: 1HZX475

| | | | |
|------------------------------------|--------------------------|--------------|-------------------------------------|
| Vinnumber: | WAUZZZ8V6FA077585 | Versionname: | A3 SB Ultra Attraction 110PK |
| First Registrationdate: | 12/11/2014 | Fiscalpower: | |
| Expertise Mileage: | 168425 | Power Kw: | 81 |
| Bodytype: | Hatchback | Body color: | Grey |
| Gearbox: | MAN 6 VIT | Paint type: | Metallic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 2632 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | |
|--------------------------------|------------------------------|
| Radio CD | Central consol F |
| Windows electric F | Luggage cover |
| Windows electric R | Front parking sensors |
| Cruise Control | Rear parking sensors |
| Steering wheel multifunctional | Type of Tow bar |
| Seats F heated | Tow bar removable |
| Radio multimedia | |
| Type of headlighting | Headlighting Halogen |
| Type of GPS | GPS big screen color |
| Type of Lining | Lining leather |
| Type of climate control | Autom climate control |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|----------------------------------|-------|-----------------------|-------|-----------------------|
| 205/55/16/91 V LightMetal | | | | |
| Summer tyres: | Fr.L. | Michelin: 3 mm | Fr.R. | Michelin: 3 mm |
| | Re.L. | Michelin: 5 mm | Re.R. | Michelin: 5 mm |

Assistance equipment

| | | | |
|--|------------|------------|--------------|
| Repair kit | Yes | Compressor | Yes |
| Total cost ex VAT | | | 95,00 |
| Alloy rim F L, Scratch(es), LI - Repair and paint (complete) | | | 95,00 |
| <i>No pictures to display</i> | | | |
| Roof, Repaired, Acceptable | | | 0,00 |
| <i>No pictures to display</i> | | | |
| Alloy rim R L, Scratch(es), Acceptable | | | 0,00 |
| <i>No pictures to display</i> | | | |