



BMW 5: 1ESQ811			
Vinnumber:	WBAXA11060DX29481	Versionname:	5 BER 525dXA St/St 211PK Aut.
First Registrationdate:	11/03/2013	Fiscalpower:	
Expertise Mileage:	125465	Power Kw:	155
Bodytype:	Berline	Body color:	Dark Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	4 Weel	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2204
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options			
Radio CD		Sun Roof electric	
Windows electric F		Central consol F	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	No Tow bar
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear			
Summer tyres:	225/55/17/97 Y LightMetal		
	Fr.L.	Fr.R.	Bridgestone: 5 mm
	Re.L.	Re.R.	Bridgestone: 4 mm

Assistance equipment	
Runflat	Yes
Total cost ex VAT	349,16
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00



Door R L, Scratch(es), Acceptable

0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete)

254,16

