



OPEL Insignia: 1HNU880

Vinnumber:	W0LGM8ER7E1166797	Versionname:	INSIGNIA BRE ecoFL.Business 120PK
First Registrationdate:	1/09/2014	Fiscalpower:	
Expertise Mileage:	195044	Power Kw:	88
Bodytype:	Break	Body color:	Brown
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3103
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	Tow bar removable
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

215/60/16/99 V LightMetal				
Summer tyres:	Fr.L.	Pirelli: 5 mm	Fr.R.	Pirelli: 5 mm
	Re.L.	Pirelli: 5 mm	Re.R.	Pirelli: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	4360,70
-------------------	----------------

Alloy Rims (all), Chemical polution, LI - Repair and paint (complete)	0,00
---	-------------



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 308,20



Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80



Rearview mirror housing R, Scratch(es), Acceptable 0,00

No pictures to display

Rearview mirror housing L, Scratch(es), Acceptable 0,00

No pictures to display

Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Wing F L, Scratch(es), LI - Repair and paint (complete) 220,18



Rocker panel inner F L, Dent(s), LI - Repair and paint (complete) 115,56



Inner seat cover L, Tear, E - Replace 59,00



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 318,35



Door panel R R, Tear, E - Replace 114,00



Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Interior, Dirty, Shampooing 200,00



Sill outer R, Dent(s) and scratch(es), LI - Repair and paint (complete) 310,50



Bumper R, Dent(s) and scratch(es), Le - Replace and paint 651,00



Door R R, Scratch(es), LI - Repair and paint (complete) 318,35

No pictures to display

Sill outer L, Dent(s) and scratch(es), LI - Repair and paint (complete) 310,50



Tailgate, Dent(s) and scratch(es), LI - Repair and paint (complete) 301,68



Bodywork, Scratch(es), 67 - Polish 0,00

No pictures to display

Bonnet, Chemical polution, LI - Repair and paint (complete) 290,08



Ignition key, Broken, E - Replace 150,00



Roof, Chemical polution, LI - Repair and paint (complete) 481,50

