



BMW 3: 1HYR089

Vinnumber:	WBA3D91080P748276	Versionname:	3 BER 316dA 116PK Aut.
First Registrationdate:	30/10/2014	Fiscalpower:	
Expertise Mileage:	162517	Power Kw:	85
Bodytype:	Berline	Body color:	Black
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2331
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Rear parking sensors
Windows electric R	Type of Tow bar
Cruise Control	No Tow bar
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	NOT OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/50/17/94 W LightMetal			
Summer tyres:	Fr.L.	Bridgestone: 2 mm	Fr.R.	Bridgestone: 2 mm
	Re.L.	Bridgestone: 4 mm	Re.R.	Bridgestone: 4 mm

Assistance equipment

Total cost ex VAT	701,68
Roof, Chemical polution, LI - Repair and paint (complete)	481,50





Wing F L, Scratch(es), LI - Repair and paint (complete)

220,18



Bumper R, Repaired, Acceptable

0,00

No pictures to display

Tailgate, Repaired, Acceptable

0,00

No pictures to display

Wing R R, Repaired, Acceptable

0,00

No pictures to display